
COS A



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	Examiner: Yogesh Aggarwal
TORU KOIZUMI ET AL.)	Examiner. Togesii Aggarwar
Appln. No.: 09/430,023		;)	Art Unit: 2615
Filed: October 29, 1999		;) ;	
For:	SOLID-STATE IMAGE PICKUP)	
	DEVICE AND METHOD OF	:	
	RESETTING THE SAME)	
U.S. Patent No.: 7,015,964 B1)	
Issued:	March 21, 2006)	July 17, 2006
Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450			Certificate JUL 2 1 2006 of Correction

07/19/2006 SDENBOB1 00000076 7015964

01 FC:1811

100.00 OP

CERTIFICATE OF CORRECTION
UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Attorney for Patentees Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

581157v1

د مین

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

7,015,964 B1

DATED

March 21, 2006

INVENTOR(S) :

TORU KOIZUMI ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 64, "red" should read --read--.

COLUMN 8

Line 64, "reduce" should read --reduced--.

COLUMN 10

Line 34, "of a" should read --of--;

Line 50, "signals" should read --signals are--; and

Line 59, "9c, the" should read --9c, the signals of the--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 7,015,964 B1

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

581157v1

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

7,015,964 B1

DATED

March 21, 2006

INVENTOR(S) :

TORU KOIZUMI ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 1

Line 64, "red" should read --read--.

COLUMN 8

Line 64, "reduce" should read --reduced--.

COLUMN 10

Line 34, "of a" should read --of--;

Line 50, "signals" should read --signals are--; and

Line 59, "9c, the" should read --9c, the signals of the--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 7,015,964 B1

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

581157v1